



Spare test beaker for service set



Only for the smoke detector test device from the service set with the product ID 2.799.330.868

Note The seal on the top of the beaker (shown in black in the figure) is not included in the scope of delivery!